


Total Land Subsidence in the Harquahala Valley, Maricopa County
Based on Radarsat-2 Satellite Interferometric Synthetic Aperture Radar (InSAR) Data
Time Period of Analysis: 1.0 Years 02/26/2013 To 03/17/2014

© MDA 2013 - 2014

Explanation

02/26/2013 To 03/17/2014

Total land Subsidence



Subsidence Feature

Hardrock

Earth Fissures

CAP Canal

Highways and Interstates

Interstate

US

State

Roads

Railway

1:200,000



0 1 2 4 6 8 Miles

Decorrelation (white areas) are areas where the phase of the received satellite signal changed between satellite passes, causing the data to be unusable. This occurs in areas where the land surface has been disturbed (i.e. bodies of water, snow, agriculture areas, areas of development, etc).

Earth fissures were mapped by the Arizona Geological Survey.
 For information on earth fissures visit: www.azgs.gov/EFC

Coordinate System: NAD 1983 UTM Zone 12N
 Projection: Transverse Mercator
 Datum: North American 1983
 Units: Meter
 Created: 1/5/2015

